


S.S. "ANGERMANALFVEN"

Submitted the Cardiff Surveyors be requested to  
state the midship thickness of the poop and upper deck  
stringers and plating, also thickness of hatch coamings,  
and number of W.C. Bldgs between fore peak and boiler  
room bulkheads

dt. 22. 4. 21



R.M.M.  
© 2020  
22.4.21.

R.B.

Lloyd's Register  
Foundation

He adds that the vessel is at present in dock at