

EX-GERMAN S.S. "ANGERMANALFVEN"

This vessel was surveyed for condition at Newcastle in September last and six months certificates issued on Form 10.

In December another survey was held on account of damage by collision and a damage survey report was issued on Form 10.

She has now been examined afloat at Dublin on account of grounding said to have been on a sandy bottom, the Surveyor states no damage has been found but he considers the vessel should be examined in dry dock at the first convenient opportunity or at the next six-monthly examination.

It is submitted the Surveyor should furnish a certificate on Form 10, stating the reason for the survey, the result of his examination and his recommendations.

APR 22

C.T.

19.2.21.



© 2020

Lloyd's Register
Foundation

W 619-0126

113