

173 SUNDERLAND.

Lloyd's Register of British & Foreign Shipping.

/ Enclosure 55, Fawcett Street,
Sunderland, 20th, May, 1914.

LOYDS REGISTER
LONDON
21 MAY 1914

Amkub's

The Secretary,
London,

Sir,

With reference to the 1st Entry Report No.26112 on the new steamer "MOORISH PRINCE" forwarded on the 18th instant, I beg to state that the Builders inform me that owing to the links of the cable supplied to the vessel being longer than usual, a difficulty has been experienced in lifting it.

A new set of cables, the particulars of which are given on the enclosed form, has been examined by me and despatched to the vessel at Stockton today.

I shall be obliged if you could make the necessary alteration on the report.

I am, Sir,

Your obedient Servant,

J. S. ...



© 2020

Lloyd's Register
Foundation

W619-0202

Build Angle, Plate, Tee Bulb or Channel				
spacing	26	26		
Upper Deck Bulkhead Bulkhead				
Deck MATERIAL and thickness				
Third, Fourth & Fifth Deck Stringer Plate				
breadth and thickness				

Referred to the Chief Ship Surveyor.

MAY 21 1914

Also for Mr. S. A. Hill to note

Handwritten initials

Handwritten signature

Handwritten text



© 2020

Lloyd's Register Foundation

Vertical handwritten text

Vertical handwritten text

Vertical handwritten text

Vertical handwritten text

Vertical handwritten text