



Lloyd's Register of British & Foreign Shipping,

97 & 98, Scottish Provident Buildings,

Donegall Square, West,

Belfast, *14th July 1910*

LLOYDS REGISTER,
LONDON.

REC^d 15 JUL 1910

ANS^d

*The Secretary,
London.*


Sir,

In reply to your letter of yesterdays date having reference to the First Entry Report 6804 on the M. St. Albans. I beg to state the butts of the middle line strake of inner bottom plating were treble riveted as required by the Rules; and shown on the copy of approved Midship section.

The particulars of riveting given in the Report. refer to the inner bottom plating; there being no space for the riveting of butts and edges of middle line strake, no particulars were given.

I am, Sir,

*Your Obedient Servant,
P. O. Kendall.*



Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

al

R.M. 15/7/10

JUL 15 1910

Also for Mr. S. A. Hill to note.



© 2021

Lloyd's Register
Foundation