

2500.12.17.

1

17 FEB 1933

Received from Chief Surveyors

Sent to Chief Surveyors

VESSEL'S NAME Steel Sc. Sr. "DUMFRIES" Report Brw. No. 2415

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.32.)

Nature of Survey When due

The vessel requires to be examined in dry dock at the first convenient opportunity, after grounding.

The 3rd S.S. No.2 became due 6.32.

The vessel is laid up indefinitely at Instow.

The attached letter has been received from the Owners.

It is submitted the Owners be referred to the Secretary's letters of the 18th and 22nd July last, respectively, in which the Committee's requirements have been fully set forth.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

*Let Down. 20/2/33
For Mr. Sprinks to note E.*



17.2.33

Lloyd's Register
Foundation
W630-0084