

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the plates, and of the inner bottom plating.

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Surveys.

COPY.

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

18th July, 1932.

Dear Sirs,

H.


I beg to acknowledge the receipt of your letter of the 16th instant and note that the steamer "DUMFRIES" is now laid up and that it is your intention to carry out the Boiler Survey before she is recommissioned.

With regard to the 3rd Special Survey No.2 I think it well to point out that in accordance with the Society's Rules the Special Surveys of Steel Vessels become due at the expiration of 4, 8 & 12 years from the Date of Build, and subsequently at the expiration of like periods from the date of the last Special Survey No.3 recorded in the Register Book. In the case of this vessel the 2nd Special Survey No.3 was held in June, 1924 and the 3rd Special Survey No.2 therefore became due at the end of last month. In the circumstances I shall be glad to learn what arrangements are proposed to be made for the inspection in question to be carried out.

I am, Dear Sirs,

Yours faithfully,

Messrs. The Anglo-Celtic Shipping Co. Ltd., pro Secretary,  
3, Pier Head Chambers,  
CARDIFF.



Lloyd's Register  
Foundation

W630-0091

...register soon without fresh record of survey subject to the vessel