

Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP NAME Stl. S.S. "THISBE".

Rpt. Nwc.

No. 71831

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)


Survey

It is submitted before this case receives consideration, the report should be returned, and the Newcastle Surveyors requested to fill in particulars of the framing, stringers, etc. in way of the quarter deck, and also the scantlings of the floors in way of the boiler space, if, as would appear from the pumping plan, the double bottom is now fitted at this part.

They should also state whether the double bottom (if fitted in way of the boiler space) has been tested in accordance with the rules for double bottom.

The approved plan, midship section, & profile should also be forwarded as is usual for reference, and the builders informed that if they will prepare copies of the same and forward to this office, they will be stamped and returned to them, if desired.

Dr. 8.5.19.

  
8. 5. 19

W633-0177



© 2020

Lloyd's Register  
Foundation