

1 DEC 1931

1

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME SS & "GIRDLENESS" Rpt. Hul No. 423/5

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Particulars of Survey DAMAGE.

Damage through heavy weather.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:-

Trawl placed on slipway, a number of rivets renewed on shell, frames & fish room minor repairs carried out.

Bottom coated.

It is submitted the vessel is worthy to remain as classed with record of Survey 11/31 as recommended.

100 A1
Shm. Handler
11/31 Hul

[Signature]

W.H.B.
1.12.31.



© 2020

Lloyd's Register
Foundation

W635-10117