

W636-0085

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

24 JUN 1930

VESSEL NAME Steel Sc.K. "LORD FISHER", Rpt. Hul. No. 40914

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92*).

of Survey _____

The Hull Surveyors report this vessel placed in dry dock, bottom coated and minor repairs effected.

All lining and ceiling in the fore and after fish rooms have been removed, steelwork cleaned, examined and recoated and new lining and ceiling fitted.

It is submitted the vessel appears worthy to remain as classed with record of survey 6.30.

100 A. I.
Steel Trawler.
6.30 Hul.



© 2020

Lloyd's Register
Foundation
24.6.30.