

W636-0264

cf. "Eburna."

New Rpt 65145.

It is submitted the Newcastle Surveyors should be requested to state whether there is a donkey boiler on board as no mention is made in their report in the place assigned at the top of the 2nd page. They should also state the date they recommend for the record of + LMC. omitted from their report.

A R L

J W D

24/11/13

W 25/11/13

Lloyd's Register
Foundation