

Owner:- Lloyd's Register

W639-0161

COPY.

The Second Special Survey No. 3 on this vessel.
is due at the end of June. The vessel has been laid
up in Suez Harbour since March 1928.

The Genoa Surveyors now forward the following
message, viz:-

The following cablegram has been received from the
Genoa Surveyor at Manila. The
purchasers desire complete repairs to the
condition hull and machinery and
the message asks please refer to the
Genoa Surveyor at Manila.

It is submitted that the Genoa Surveyor at Manila
should be held, as will be seen from the following
Special Survey No. 3 on this vessel.

WLT REGISTER
MANILA

(23.7.29)

PINCIO SECOND NUMBER THREE DUE JUNE LAST SHOULD NOW BE
HELD GENOA SURVEYORS COULD BE AUTHORISED SURVEY VESSEL
BEHALF INTENDING PURCHASERS WITH VIEW MAKING
RECOMMENDATIONS AS FAR AS PRACTICABLE ANY NECESSARY REPAIRS
SUBJECT WRITTEN CONSENT PRESENT OWNERS STOP COULD NOT
AUTHORISE SURVEYORS MAKE ESTIMATE COST SECOND NUMBER
THREE OR EFFECTING NECESSARY REPAIRS

COMMITTEE

56 @ 100 ~ 42.68



© 2020

Lloyd's Register
Foundation