

2m, 3, 10.

1

Sent to Chief Surveyors

15/6/10

Received from Chief Surveyors

VESSEL'S NAME

St St Roseric'

Report

Ln

No.

15800

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ 100 A.I. (Old) "Shells" done with putty
2 8" (etc) & done framing & shells as (etc. W.S.)
NB: but also a 13" u to 24" f 173 112" P.T. 43 103/16 A.P.T. 25
F.K. 50H to u. as, 13.H to M. as, but Lloyd's 2x60.

Mr

RBA

15/6/10



© 2020

Lloyd's Register
Foundation

W639-0216

" Angle on upper edge
" Spacing
PILLARS, In 'tween Deck, size and spacing

2 1/2	52	-	2 1/2	52
-------	----	---	-------	----

" Angle on upper edge
" Tie Plates
" Deck, Material and thickness

Steel deck, whole length
Pitot line