

9.6.20

"Fort Victoria" ex "Willochra"

The British Corporation surveyor states that the propeller shafts were drawn in and examined by them last November & were then found in order.

3 propeller blades which were bent at tips were then renewed

Thomas R Blackie

21, Fenchurch Street, London, E.C. 3.

Trade Register of 2019



Lloyd's Register
Foundation
1641-0003

S. COMMITTEE, FEN, LONDON.

TELEPHONE: CITY, 8160, 8161 & 8162.



Lloyd's Register of Shipping.

71, Fenchurch Street, London, E.C. 3.

address
communications
subject to
SECRETARY
the following
rules.

[Faint, mostly illegible handwritten text, likely bleed-through from the reverse side of the page.]



© 2019

Lloyd's Register
Foundation

ANS