

NEW YORK

March 12, 1920.

JOHN CARNEGIE

the Owners' Representative survey the S. S. "FORT VICTORIA" of Liverpool, 7784 tons gross register while she was afloat at Pier 95, North River, New York on March 6, 1920 for the purpose of ascertaining the nature and extent of damage stated to have been sustained through heavy weather encountered on the 3rd of March, 1920 while on a voyage from New York to Bermuda.

For further particulars see Log Books.

The undersigned upon examination:-

FOUND

One sidelight on the starboard side in way of No. 1 lower 'tween decks broken, together with iron plug and deadlight the opening being temporarily closed by a bolted steel plate.

RECOMMENDED

New sidelight with iron plug and deadlight to be fitted or the opening permanently closed by fitting a rivetted spigot patch as proposed by the Owners' Representative.

FEE \$25.00



© 2019

Lloyd's Register
Foundation

W 641 - 0023