

W652- 0143

Received from Chief Surveyors

M^r S^r HOGARTH

Report *Liv*

No. *97570*

For the CHIEF SHIP SURVEYOR ~~WHICH IS THE CASE~~

which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

1st No. 2

SURVEY *advanced* ~~PARTLY HELD.~~


12.29

When proposed to be completed *within the year of grace—agreed to.*

To complete the Survey repairs:- See Report.

Liv 95984

The stem frame repaired by E.H. 7.24 + 9.29 to be specially examined at next dry docking & riveted plating to be permanently repaired at first convenient opportunity.



© 2020

Lloyd's Register
Foundation