

COPY.
PORT OF

W652-0144

5th September, 1930

sirs,

With reference to the classification in the
City's Register Book of your steamer "HOGARTH", I
to acquaint you that to complete the special survey
the following remains to be done, viz:-

"Vessel to be placed in drydock, bottom and
rudder cleaned and examined, chain locker
to examine, and anchors and cable to be
ranged and examined. No.2 tank top coaming
angle in way of manhole starboard side to
rerivet. No.1 hold starboard side aft one
shell rivet to renew. Port shell plate
A.5, B.5 & C.5 from forward and 6 floors
and 5 intercostals in No.1 double bottom
tank, starboard shell plates C.5 and 4
floors and 3 intercostals in No.1 double
bottom tank, to be dealt with"

"All sea cocks and valves and under water
fittings to be examined"

I am, Dear sirs,

Yours faithfully,

Secretary to the
Liverpool Committee.

rs. Lamport & Holt Ltd.,
r Building,
RPOOL.

© 2020

Lloyd's Register
Foundation