

SEE SFO. REPORT NO. 5317.  
COPY.

# Lloyd's Register of Shipping.



SAN FRANCISCO,

Port

November 16th, 1927.

**This is to Certify** *that I have*

*Surveyed the* Steel Twin Screw Steamer "ARIZONAN", of New York,  
8511 tons gross register, while lying afloat at this Port on  
account of accident to sump box on November 13th, 1927 - - -

-----  
*and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report, stating that all repairs  
recommended by me have been completed to my satisfaction, and  
that I have Recommended that she be retained as now classed  
without fresh record of survey* - - - - -

-----  
*being fit to carry* dry and perishable cargoes.  
-----

(Sgd) S J READER

Surveyor to Lloyd's Register.

ACTING

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."