

Surveyors 6. 4. 22

Received from Chief Surveyors

NAME Mr. J. Dalmaker

Report

GRS

No. 39835

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

When due

Survey

The main condenser was damaged when being placed on board, it was temporarily repaired & the vessel's class is continued subject to a new condenser being fitted on board at the first convenient opportunity.  
It is submitted the Antwerp Surveyors be advised of this by wire.

GRS

6/4/22

Lloyd's Register  
Foundation

11655 0166