

Attach to Off Rpt no. 45738

REPORT OF TOTAL LOSS, CASUALTY, &c.

7260

WRECK BOX

No. 51 Top

No. 67461 in R. B. Wreck Book, p. 123

Date of writing this report 13th October 1924Vessel's Name *Steel S.S. "Courtown"* of *London* Tons {Net 2714
Gross 4419Built at *South Shields* When 1909 Casualty notice sent to Owner 10.10.24 Owner's reply *Attached*Owner's Name *Torion Line (London) Ltd. (Harrison Sons & Co. Agents)*Address *Dowdall's Chambers, Cardiff*

SOURCE OF INFORMATION.

Case previously before

Date

Classing Committee.

Last Minute

Particulars of Classification.

+100A1
Sheltered
with fbd. +EMC9.23

Date of Casualty

20th September 1924

Précis of particulars of Casualty

*Vessel was sunk by collision 3 miles
north of Pendeen, on 20th Sept., 1924.
Owners concur.*

COURTOWN.—Land's End Wireless Station, Sept. 28.—Steamer Courtown in collision with steamer LA ROCHEFOUCAULD at 1 30 a.m. Sept. 28 south of Pendeen.

Penzance, Sept. 28. — Steamer Courtown seen to sink at 6 40 a.m., about three miles north of coast-guard station.

Land's End Wireless Station, Sept. 28.—Steamer Courtown sank at 6 40 a.m. (G.M.T.), three miles north of Pendeen, after collision with French steamer LA ROCHEFOUCAULD. All crew saved and on board the LA ROCHEFOUCAULD, proceeding Penarth.

Record


Committee

TUES. 14 OCT 1924

Sunk by collision 9.24

tee's Minute

10.24

Sunk by collision 9.24

© 2021

Lloyd's Register
Foundation