

Compulsory

Copy

Are the liners between the plates and plates sufficiently countersunk in the plate to plate, &c., conform well to each other? *Yes* Are the rivet holes well and sufficiently countersunk in the plate? *No*
from the faying surfaces? *Yes* Do any rivets break into or through the seams or butts of plating? *No*

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port *Liverpool* (When received in London Office)
Vessel's Name *St. Highland Loch*
Official No. No. in Reg. Book *48 Sup.*
Port of Registry (For Foreign Vessels) */*
Iron or Steel State whether Classed by Lloyd's Register *Yes*
Name of Owners *H & W. Nelson, Ltd.* Date of Verification *March 7th 1911*

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	<i>3</i> ft. <i>10</i> ins.
From centre of disc to top of statutory deck line } at awning or part-awning deck . . . }	ft. ins.
Fresh water line above centre of disc . . .	<i>6 1/2</i> ins.
Indian Summer line above centre of disc . . .	<i>6</i> ins.
Winter line below centre of disc . . .	<i>6</i> ins.
Winter North Atlantic line below centre of disc	<i>✓</i> ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wooden iron deck with the vessel's side { at main spar or upper dk.	<i>1 3/4</i> ins.
{ at awning or part-awning dk.	ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

(Signed) *S. G. Kash.* Surveyor.

(To be filled up in London Office.)

Statement No. *21469* Date of Committee's Minute *21.2.11*
Moulded Depth for record *29* ft. *8* ins.
Freeboards compared and found correct by date *9.3.11*
Is fee paid? *new Vessel* Form for Certificate *A* © 2020
Instructions date
Certificate written Noted for posting

2m, 8, 10.—T.



© 2020

Lloyd's Register Foundation
W658-0003

Classification 100A1 Shelter Deck conditional on the above freeboards.

State whether the Vessel has been built under Special Survey *Yes*
If of opinion this Vessel should be Classed ** 100A1 Shelter dk with hull*

Wm. H. Na