



Lloyd's Register of Shipping,

Willemskade, 11^B,

Rotterdam, 6th December 1934,

(Postbox 701.)

Communications to be addressed to—
SURVEYORS.

Dear Sir,

In reply to your classing letter of the 4th inst. respecting the new boilers now placed in the s.s. "SINT JANSLAND" I beg to inform you that the size of rivet holes in the shell seams are 1.3/16, pitch in circumferential seams $3\frac{3}{4}$ and depth of girders $8\frac{5}{8}$, all as approved.

The grate surface of each boiler is 50.5 sq. ft. as in the original boilers.

I am, Dear Sir,

Yours faithfully,

The Secretary,

London.



© 2021

Lloyd's Register
Foundation

W 66-0007

1K 66-0010

7 DEC 1932

1894

.tant nta ent to rettel ghtassig tuoy ot vlyer ni
 "VING" .s.e ent ni besediq non arelled wen ent ghticoseat
 selod tevir to eais ent tant uoy mroft ot ged I "MALMAL
 leithereimuric ni notiq ,dl\l are amee lleds ent ni
 .bevorqas aa lla ,dl\l aredng to ntqeb hns ll amee
 as .tt ,pa dl\l rettel hns to esctus eters ent
 .rettel lantigiro ent ni

Willemskade, 11 B.
Amsterdam

TELEPHONE 203-2032

DATE RECEIVED: 10/10/10

© 2021

Lloyd's Register
Foundation

Periodical
cause of
on account
and besi