

full particulars of the case immediately.

S.S. "RABAT"

It is submitted that the Hamburg Surveyors should be requested to carry out the survey for this vessel as desired by the Owners. They should also be requested to state if this vessel is a sister ship to the S.S. "MELILLA" at present under their survey.



© 2021

*H.R.*

13.6.21.

Lloyd's Register  
Foundation

W661-0047

holes — Distance between rings — Working pressure by rules — End plates: Thickness —

Working pressure of end plates — Area of safety valves to superheater — Are they fitted with casing

scri  
tes  
of m  
Mate  
Back  
ts  
e by  
Dona  
rules  
rial  
Work  
uck 2  
nber  
nd pite  
uperheat  
on of lo  
of flue p