

in damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) and painted on Ship and now verified

26 JUL 1934 11

by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME *Stl S. M/V WINTON* Rpt. *Syd.* No. *13742*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

of Survey

The *Sydney* Surveyors report this vessel placed in dock, bottom cleaned and coated, *bilge keels repaired* and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey *6.34* as recommended.

*100A.1.*  
*with freeboard*  
*6.34 Syd.*



© 2020  
Lloyd's Register  
Foundation  
*2H 7 34*  
*W663-0451*

General Observations, Opinion as to Class, Recommendation, etc.

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book without fresh record of Survey, "to remain as classed for example:—"