

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME Stl. Sc. "MAID OF SPETSAI"

Rpt.

Nwc.

No. 77447

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

The class of this vessel is subject to some indented shell plating being dealt with at the Owners' convenience and to a length of chain cable being repaired and retested or renewed at the earliest opportunity.

The Newcastle Surveyors now report the vessel placed in dry dock, the bottom cleaned and coated and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 1,24, subject as above.

100A1

1,24 Shl.

} subject, etc.

Fitted for oil fuel, etc.



© 2021

Lloyd's Register
Foundation

W678-0279