

SPECIAL NOTE.

Vessel has excess auxiliary
power but will not be
necessary to survey whole
of auxiliaries at S. Surveys



© 2019

See Clip C.F.L.
Lloyd's Register
Foundation

W68-0108

XXXXXXXXX Machinery of this vessel

On request of the owners representative examined the main