

W680-0190

24 AUG 1931

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Stl. S.S. "VULCANUS". Rpt. Sng. No. 4925.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92).

Survey

The 2nd S.S.No.2 became due 5,31 and a proposal to postpone same until the vessel is again due for re-employment has been agreed to.

The Singapore Surveyors now report the vessel placed in dry dock, bottom coated, 3 doubling plates fitted to shell plating in way of the engine room where locally wasted, and minor deck repairs carried out.

The vessel is now laid up at Singapore.

It is submitted action be deferred.



© 2020

Lloyd's Register
Foundation
21.8.31