

SINEER, COPENHAGEN.

TELEPHONE NO. 5760.



LLOYD'S REGISTER
RECEIVED
12 NOV 1931
Ann.
LONDON

be addressed
YORS,
Shipping,
K.

Lloyd's Register of Shipping.

28¹, Sankt Annæ Plads,
Copenhagen, K. 10th November 31.

The Secretary,
Lloyd's Register of Shipping,
London.

Dear Sir,

We have to confirm our cablegram of to-day, viz:-

Decoded:- "Petsamo referring to your cable of yesterday
 "regarding main boiler steel plugs caulked from
 "outside cannot be removed unless disturbing
 "threads in holes necessitating still larger
 "plugs stop Buttstraps specially examined
 "internally and externally and found in good
 "condition stop Owners most urgently request not to
 "remove plugs Burmeister consider fitting of rivets
 "most unsatisfactory plan forwarded to-day".

The plan in question is herewith enclosed.

I am, Dear Sir,

Yours faithfully,

J. Hansen

SURVEYOR TO LLOYD'S
REGISTER OF SHIPPING

Lloyd's Register
Foundation

W69-0172




Lloyd's Register
Foundation



[Large Handwritten Text]

Coburgstein K. Toto Mowmpet H.

58, Sankt Anna Plaza,



London.

RECEIVED
REGISTER OF SURVEYORS
CITY OF HAMBURG, K.

201

811.

"We have to consult our colleagues at Noda, Aizu:-
"regarding the toll rates of Mount Gassan to Aspernab-

"onwards to remove John Edmond from our plan prior
"which was in poor condition after plan prior
"but was soon superseded by the new plan prior
"which was soon superseded by the new plan prior
"and so on until we reached Noda, Aizu:-

"In the meantime we have been examining the new plan prior
"and so on until we reached Noda, Aizu:-

"and so on until we reached Noda, Aizu:-

"and so on until we reached Noda, Aizu:-

I am, dear Sir,

Yours truly,
John Edmond

J. E. B.

12 NOV 1931

Special Dam
(not to write)
Travelling F

10m.730.

REASSEMBLED 20 NOV 2
SURREY 20 NOV 2

REASSEMBLED 20 NOV 2
SURREY 20 NOV 2

Referred to the Chief Engineer Surveyor.