

CABLEGRAM received from the Surveyor at COPENHAGEN.

Date of receipt: 10.11.31.

## TRANSLATION.

PETSAMO - Vessel's Name

ERFOW - Referring to your cable of  
 TIVIT - yesterday  
 OKVUW - regarding  
 ALUHD - main boilers  
 SAGXU - steel  
 NEJLE - plugs  
 ETYRX - caulked  
 KEBEZ - from ? MINECI = outside.  
 MUECI -  
 ESYSE - ~~could~~ be removed cannot  
 SRAIX - unless  
 GHEXA - disturb  
 threads  
 KYBUZ - in  
 KUFGA - holes  
 MAGYP - necessitate ? SAXAW = still  
 SAXAN -  
 LIHDA - larger  
 NEJLE - plugs  
 SAZPO - stop  
 EPKET - Buttstrap(s)  
 PHUAT - specially  
 JESDU - examined  
 LATHI - internally and externally  
 ADIMT - and  
 JYKAX - found in good condition  
 SAZPO - stop  
 MNYES - Owners  
 LYKYP - most  
 SUCMI - urgently  
 ORWOX - request  
 MARJE - not  
 SMOIJ - to  
 OLTHU - remove  
 NEJLE - plugs  
 Burmeister  
 FASJY - consider  
 JUMAV - fitting of  
 OVMUG - rivets  
 LYKYP - most  
 SRYON - unsatisfactory  
 MYWID - Plans forwarded  
 SNEPI - today.



© 2020

Lloyd's Register  
 Foundation

W69-0115