

W692-0144

ACTING SURVEYOR TO LLOYD'S REGISTER

C/O Surveyor of Ships' Office,  
Penang, 14th April, 1938.

Sir,

I have today forwarded by Commercial Papers  
Post Report 8 and a copy of Report 10 for the M.V. "TONGKING"  
(No. in Reg. Book 35292).

In Report 8, I have recommended that the vessel  
be expunged from class and that her particulars be deleted  
from the Register Book, since the vessel is to be sold by  
the Underwriters as she lies, burned out and aground.

As this case has presented some unusual features,  
I should be glad to have any comments on my report.

I enclose some press photos and others taken by  
myself which may be of interest.

Yours faithfully,

*E. Watt*Ag. Surveyor to Lloyd's Register,  
P e n a n g.

The Secretary,

Lloyd's Register of Shipping,

71 Fenchurch Street,

LONDON, E.C.3.



© 2020

Lloyd's Register  
Foundation



Referred to the Chief Ship Surveyor,  
and the Chief Engineer Surveyor.


22 APR 1938

Also for Mr. Hill to note.

also for Mr. Sladden to note.

Referred to Mr. Dyer.

*For Mr. Dyer*



© 2020

Lloyd's Register  
Foundation

