

REPAIRS DUE TO WEAR & TEAR:-

Bottom half of stern tube lignum vitae renewed.

ME bilge suction valves and seats renewed.

15 smoke tubes in main boilers renewed.

21 small stays in CC's renewed.

Loose seat in Starb. Boiler main stop valve renewed.

*B.S. due 12.25. held machinery also
examined Xeroxworthy due 12.23 done*

N.B. - If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

*It is submitted that
this vessel is eligible for
THE RECORD. + L.M.C. 12.25*

12.25

*H.
2/2/26*

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation