

Rpt. 14.

GRIMSBY

Port of

1st December, 1926. 10

## REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs,

Having, in accordance with your instructions, examined the Masts, Spars, and Rigging, and Iron Work of same, of the  
*s.s.* "PLODDER"

I have to report that I found one shroud broken on the main mast and all other work in wire rigging in good condition. The shroud above mentioned to be renewed.


George Bromfield

Fee £ - 10 - 6'

To the Surveyors,

Lloyd's Register of British &amp; Foreign Shipping,

GRIMSBY.



© 2020

Lloyd's Register  
Foundation