

Damage No 2.

Port side in way after hatchway: - One bulwark plate

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

15th November, 1926.

Dear Sirs,

With reference to your letter of the 12th

The Secretary,

H. Lloyd's and mine of the 15th ultimo relative to the steamer "PLODDER",
E. C. 3.

I shall be much obliged if you will kindly let me know, for
the information of the Committee, whether you are yet in a

Dear Sir,

position to say when and at what port an opportunity will
occur for the Boiler Survey of this vessel to be carried out.

I am, Dear Sirs,


Yours faithfully,

Clerk to the

Classification Committee.

Messrs. Striver Steamship Co., Ltd.,
Cory Buildings,
117, Fenchurch Street,
E.C.3.

Cy



© 2020

W695-0082

Lloyd's Register
Foundation