

Port side in way after hatchway: - One bulwark plate
removed, one removed, painted and repaired and one

3m.10.25.

POSTPONED SURVEYS.

Case of the Stul ss. "Plodder"

No. 80786 in Reg. Bk. 519/283 tons, Built 1918-7mo

Classed +100A1 Owners N. Harrison
5. 15.

Port of Registry London
Sp. No. 1-23 + LMC 2. 24 Ct. 4. 15
BS. 5. 15 + NB. made 99 refitted 18.

Survey due Boiler Survey due May, 1926
Sp. No 2 due July, 1926

The Owners state they hope to be able to make the necessary arrangements for the Boiler Survey when the vessel next arrives in London. They add they will advise this Office in due course when they propose to have the Special Survey No.2 carried out.

Submitted action be deferred.

Ans. 19.7.26.

TUES. 20 JUL 1926

Committee's Minute

Decision

Deferred



© 2020

Lloyd's Register Foundation

W695-0089

tinger
length
the
to
such
carried
place
over
in
d.
f.
acted
by