

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

The donkey boiler for the vessel built and installed under special survey in accordance with the approved plans, the material tested to the requirements of the rules of the Society, and the workmanship of good quality. Tested by hydraulic pressure to 240 lbs. and the safety valve adjusted under steam at 160 lbs.

Certificate (if required) to be sent to
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	:	:	When applied for,
Special £	:	:19.....
Donkey Boiler Fee	:	:	When received,
Travelling Expenses (if any) £	:	:19.....

Committee's Minute *New York JUL 8 - 1919*

Assigned

See Sea Rpt 549

James Fowler
Engineer Surveyor to Lloyd's Register of Shipping



© 2020

Lloyd's Register
Foundation