

W696-0155

3m.4.21.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Steel S.S. 'Mahavohio' ex Isis*

Report *His*

No. *82392*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

When due

*See Separate endorsement regarding the omission of tween deck bulkhead dated 12<sup>th</sup> July 21.*

*100. A.1. (Steel) "with foreboard"*

*3 Dks (Steel) A<sup>th</sup> DK (Steel) in N<sup>o</sup>. 1 Hold*

*Cell TB a 165' vF29' f221' 1613t*

*FK, "Tween deck bulkhead in forward hold dispensed with, Seven BH to upper DK  
One BH to Second deck only," Cw, P41'B136' F53'*

*Date of build 1915*

*7.21 Bkn*

*S.S. Bkn N<sup>o</sup> 3 - 7.21.*



© 2021

Lloyd's Register Foundation

Freeboards compared and found correct by \_\_\_\_\_ Date \_\_\_\_\_

Is fee paid? \_\_\_\_\_ Form for Certificate \_\_\_\_\_

Instructions \_\_\_\_\_ Date \_\_\_\_\_

Certificate written \_\_\_\_\_ Noted for posting \_\_\_\_\_

01  
43  
1  
34