

VESSEL'S NAME S.S. Barone Edmonds Vailj. Report Gls. No. 20085

Remarks of the CHIEF ENGINEER SURVEYOR for the consideration of the Classing Committee.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Surveyor First Entry.

If only partially held, the Committee require in each case a brief statement of the following, amongst other particulars:—

When Survey became due

When proposed to be completed

Remarks:—

It is submitted the Belfast Surveyors be requested to state if the blow off cocks are fitted with a spigot and brass covering plate.

Ir to Bel 30.7.02

C.M. 30.7.02

J.S. 30.7.02



© 2020

Lloyd's Register Foundation

Material of stays Iron Area Diameter at smallest part 2.03 Area supported by each stay 6.4 Working pressure

f Screw shaft as Size of Cran other moveable other is at other is at Suctions co 1/2" - 4- nkey suction e sluices on E ts Bo discharge pip cocks fitted protected e at all tin and the b the screw 78 # 180 W 56.75 185 W 3" Length seams width Size of M did 8764