

st. shaft.

16004E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

"PACIFIC RANGER"

Rpt.

Vcr.

No.

5453

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)


of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Continuous Survey advanced.

It is submitted the vessel is eligible to remain as classed and WILL BE eligible for the record BLMC CS and date, when the survey has been completed.

To complete the survey:- See Form 7E.



Lloyd's Register
Foundation

Yam

15.10.40.

1X70-0002

ection all receivers, after 43)
Main Engines. 4

Aux. Engines. 705