

COPY.

-2-

Continued:-

The position where the vessel now lies makes road transport almost impossible, and also very dangerous from the sea.

I consider that there is little hope of salvaging any quantity of the cargo.

Signed:-

P. Word.

The Manager.

Maritime Insurance Coy.

CAPE TOWN.



57



© 2020

Lloyd's Register
Foundation

W703

- 0024

W

HAMLET. — Cape Town, Apr. 8. —
ing steamer Hamlet ashore outside
danha Bay; reported back ap-
broken. Will probably be a total
loss.

HAMLET. — Cape Town, Apr. 8. —
ing steamer Hamlet, which went
at South Head, near the entrance
danha Bay, during foggy weather
Apr. 7, was bound from this port
danha Bay, with coal and whaling
She is lying in an exposed position
water and with her back appa-
ken, and will probably become a
wreck.

LET. — Cape Town, Apr. 14. —
returned from the scene
coasting steamer Hamlet
the portion forward
lost completely par-
the vessel. Af-
of, stokehold,
board side, are
extending
er. The funn-
ere breaking al-
surveyor is of opin-
possible hope of salv-
and be reckoned a
cargo.

Mr. Over
at P.
45m.

© 2020
Lloyd's Register
Foundation

 $\bar{c}_{c,11,2}$

Suggested Record
Date of Commitment
Committee's Mission