

B.L. due 5.23. partly held stated will be
completed before the vessel goes into commission
The survey also covered over hauled repairs
A number of small repairs effected
to boilers.

It is submitted that this
vessel will be eligible for
the record B.S. 10.23 when all
safety valves have been adjusted
under steam.

20/11/23

The surveyor should be
informed that before a
later date than 10.23
can be assigned he
must satisfy
himself that no
deterioration has
taken place &
state as on
his report.

This Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2021

Lloyd's Register
Foundation