

R. S. TAYLOR,
SURVEYOR,
THE INST. NAVAL ARCHITECTS.
OFFICE No. 562
PRIV. RES. No. 1045
CABLE ADDRESS:
"SURVEYOR."
CODES:
B, A. E. O. AND STANDARD.

Lloyd's Register of British & Foreign Shipping,

EAGLE STREET,

RST/CP

LOYD'S REGISTER
LONDON.
16 FEB 1915
REC'D
ANSI

Brisbane 30th December 1914

Sir,

Reverting to my letter of the 28th September in connection with the Steamer "BINGBBA" 2092 tons, and No. 728 in Register Book having in view the third paragraph of your letter dated 13th August dealing with the possible re-classification of the above Steamer, I beg to state that I attended from time to time at the A.U.S.N. Coy's Workshops during the refitting of the machinery; I also inspected the repairs as carried out to the hull, and also surveyed the vessel in dry dock; and now to-day I am in receipt of the enclosed from the Marine Superintendent of the A. U. S. N. Coy.

Owing to the irregularity of the Mails I am not able to send full report, but by the next out going mail I will submit a report for the favourable consideration of the Committee for the re-classification of this steamer.

I am, Sir,

Your Obedient Servant,

R. S. Taylor
Surveyor.

A. Scott, Esq.,
Secretary,

LONDON. E.C.

Encl/



© 2021

Lloyd's Register
Foundation

W707-0182

Referred to the Chief Ship Surveyor
and the Chief Engineer Surveyor.

FEB 16 1915

Also for Mr. S. A. Hill to note!

To await report.

JW

M
16-2-15

RECEIVED
MAR 10 1915
NAVY DEPT
WASHINGTON



© 2021

Lloyd's Register
Foundation

TELEPHONE (Office and
LONDON) 1-2000
LONDON 1-2000
LONDON 1-2000