

they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Occasional Slipping Survey on 29th April and subse  
HULL (OUTSIDE). This was thoroughly cleaned and scrubbed down for examination and

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

9th April, 1924.

Dear Sir,

With reference to the classification in this Society's Register Book of the steamer "NGAHERE", I beg to remind you that this vessel's Screw Shaft became due for survey at the end of last month, and I shall be much obliged if you will kindly let me know, for the information of the Committee, what arrangements are proposed to be made for this inspection to be held.

At the same time I may point out that the steamer will become due for Annual Boiler Survey at the end of the present month.


I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

Reginald J. Speller Esq.,  
Cory Buildings,  
FENCHURCH STREET,  
E.C.3.

*CSL*



© 2021

Lloyd's Register  
Foundation

Character Assigned

*Not for*

down fr  
th new p  
hole rece  
f poop i  
ception t  
et to li  
or exami  
r. Ther  
gin angl  
ld bulkh  
stal in  
No  
or Y.M. of Wood  
ate (on Felt.)  
en put on, Month  
Yards, &c.....  
ion, how ascertain  
te if wedges  
sent letter  
s, No. of 3 S  
(State if now  
length 210  
(on board)  
Rule length  
& Warps  
g & Running B  
ne Register B  
as classed an  
sual Se  
ting wh  
furthe

REPS  
The S  
LI  
Dear  
and t