

1.

Sent to Chief Surveyors 24.12.07

Received from Chief Surveyors

VESSEL'S NAME S.S. Swan

Report

No.

10998For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

To complete The Machinery Survey with a view to classification The fitting of the sea cocks & valves & stem tube require to be examined in dry dock.

The Owners need state that at the vessel's next stoppage they will put ~~her~~ her on the slip & have this matter attended to.

It is submitted that as this vessel is not yet classed, no further action need be taken in the meanwhile.

A.R.K.

24.12.07

© 2021

Lloyd's Register
Foundation

W717-0004