

Rpt. Rio. No. 1199.

No. 1199.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey

The class is subject to three plates on the port bow being renewed at the first opportunity, within 12 months from March, 1919.

March, 1919.

Some damage through grounding requires to be repaired at the first opportunity.

at the first opportunity.

A proposal to hold the survey on vessel's arrival at Genoa, or on her return to Rio de Janeiro, was agreed to in June last.

states he is informed

last.

The Rio de Janeiro Surveyor now states he is informed the survey will be carried out on vessel's return from her present voyage.

It is deferred for a short

It is submitted action might be deferred for a short time.

9. 12. 20.

© 2021

Lloyd's Register
Foundation

Surveyor to Lloyd's Register of Shipping

TUE. 26 JUL 1951

JUL 20 1921

Committee's Minute