

LLOYD'S REGISTER OF SHIPPING,
17 BATTERY PLACE,

NEW YORK June 26, 1917.

LLOYD'S REGISTER
LONDON.

Sir;

I enclose herewith a letter dated the 19th instant
ved from the Society's Surveyors at San Francisco regarding
Report No.2525 from which it appears that an error has been
in preparing the report-steamer "WAR KNIGHT" -The cellular
e bottom should read .52 under boilers, and not under engines.

I am, Dear Sir,

Yours faithfully,

J. French

Secretary
LONDON.



© 2020

Lloyd's Register
Foundation

W721-0116

Referred to the Chief Ship Surveyor.

JUL 24 1897

Also for Mr. S. A. Hill to read

M
24.7.12

W. H. H. H.

W. H. H. H.

W. H. H. H.

W. H. H. H.

W. H. H. H.

W. H. H. H.

W. H. H. H.



© 2020

Lloyd's Register
Foundation