

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.

22nd January, 1918.

Dear Sirs,

With reference to the classification in this Society's Register Book of your steamer "WINGA", I beg to acquaint you that the Committee have had before them a report received from the Society's Surveyor at Christiania, from which it appears that the vessel has been examined as far as practicable afloat, and by a diver after grounding. So far as could be seen some damage appears to have been sustained in way of the fore peak and No.1. double bottom tank, and temporary repairs to the fore peak have been carried out.

The Surveyor recommends, however, that permanent repairs should be effected on the vessel's arrival in the United Kingdom, and I shall be pleased to learn, at what port the vessel will be dry docked and repaired.

I may add for your information that the vessel will be come due next month for the Special Survey No.3.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. Glen & Co.,
153, St. Vincent Street,
GLASGOW.

© 2021

Lloyd's Register
Foundation

W725-0038