

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

Rpt.

No.

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

It is submitted that before this case receives the consideration of the Committee the Glasgow Surveyors should be informed that this vessel has proceeded to their port, where her machinery is to be fitted, and in order to complete the survey on the hull, the Engine & Boiler Casing requires to be riveted up.

They should be requested to give the case the necessary attention, and on completion of the work to forward a report on Form 8 in the usual manner with a view to the classification of the vessel.

R. 19/12/12

M.

19. 12. 12.



© 2019

Lloyd's Register  
Foundation