

BALCATTÀ. — Concepcion, Feb. 17. — Motor vessel Balcattà lying in a position dangerous to navigation south-east of Quiriquina Island. Masts had to be cut away in order to bring vessel nearer island. Damage sustained Lobitos consists strakes and keel torn away for a length of 40 ft. Now repaired temporarily and estimated capable resisting return home. Master calling for tenders to place vessel upright position including pumping out preparatory to docking. Agree with action master proposes. Divers report engines deck fittings intact.—Lloyd's Agent per Salvage Association.

*Per Lloyd's List
dated February
19th 1921*

Annual Survey of Oil Engines due 10.20

of deckload.

BALCATTÀ. — Concepcion, Mar. 19. — P Motor vessel Balcattà: Salvage operations successful; now upright position. Is being R pumped out preparatory to being towed into dock Talcahuano.—Salvage Association.

*Noted
96
24-2-21*

© 2021

Lloyd's Register
Foundation

W734-020

22/3/21