

REPORT of SURVEY for REPAIRS, &c.

| | | | | | | | |
|------------------------|-----|--------------------------------|--------------------------------|--------------------|---------------|-------------------|--------------------------|
| Date of writing Report | 19 | When handed in at Local Office | 18/7/07 | to | Port of | Grunshi | |
| No. in Reg. Book. | | Survey held at | Grunshi | Date, First Survey | X | Last Survey | 11 th /1/1907 |
| | | | | (No. of Visits) | one | | |
| | | | L. H. Clitus | | Master | | |
| | | | 1184 on the Wood, Iron & Steel | | | | |
| TONNAGE:- | | Built at | Selby | By whom | Cochrane & Co | When | YEAR MONTH 1905 . 6 |
| GROSS | 240 | Owners | Gruith S. J. C. Ltd. | | | Port belonging to | Grunshi |
| UNDER DECK | 222 | Owners Address | | | | | |
| ET | 98 | | | | | | |

Surveyed ~~Afloat or~~ in Dry Dock? _____ Name of Dock Asht. Destined Voyage Ashtung.

V^o*B* = Cell *D* Bar *D* Ba _____ feet; *u* *E* & *B* _____ feet; *f* _____ feet;
 total capacity _____ tons. *FPT* _____ tons; *APT* _____ tons; *MT* _____ feet _____ tons.

Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements).

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the inside of the tanks examined. Also state the amount of deterioration (if any) found in the thickness of the floors, framing, girders, and of the inner bottom plating, especially if in the boiler space.

| CHARACTER. | Years assigned now or anticipated. | Machinery and Boiler Surveys (including date of N.B., if any). |
|--|------------------------------------|--|
| ✕ for Special Survey. Date of last Survey and of Periodical Surveys | | |

Last Report, No. 452 Port 27m3

Society's Freeboard (if assigned) as
painted on Ship and now verified { ft ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? ☒ also whether any damage report was made, and, if so, by whom? ☒

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual survey

The bottom trawler cleaned, examined re-coated.

| SUMMARY OF DAMAGE REPAIRS:— | | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items:— |
|--------------------------------|-------------|--|----------------|------------|---------|--------|--------------|-------------|---------------|
| Renewed | | | | | | | | | |
| Removed and Fair'd or Repaired | | | | | | | | | |
| Painted or Re-painted in place | | | | | | | | | |
| PRESENT CONDITION OF THE | | Stringers | — | | | | | | |
| Decks | <i>Good</i> | Inner Bottom Plating | — | | | | | | |
| Caulking of Decks | " | State if Tanks have been examined inside | — | | | | | | |
| Waterways | " | State if Tanks now tested. | — | | | | | | |
| Coamings | " | Bulkheads | — | | | | | | |
| Beams & Fastenings | <i>Good</i> | Ceiling | — | | | | | | |
| Outside Plating | " | Cement or Plaster | — | | | | | | |
| Caulking of ditto | " | (State which.) | <i>Good</i> | | | | | | |
| Rivets | " | Rudder | — | | | | | | |
| Breasthooks & Crutches | <i>Good</i> | Windlass | " | | | | | | |
| Transoms | <i>Good</i> | Have Pumps now been examined and found efficient? | <i>no</i> | | | | | | |
| Frames | <i>Good</i> | Have Sluice Valves now been examined and found efficient? | <i>no</i> | | | | | | |
| Reverse Frames | <i>Good</i> | Have Watertight Doors now been examined and found efficient? | <i>no</i> | | | | | | |
| Floors | <i>Good</i> | | | | | | | | |
| Keelsons | <i>Good</i> | | | | | | | | |
| | | Ding. Plates under Seaming Pipes | — | | | | | | |
| | | Engine Room Skylights | <i>Good</i> | | | | | | |
| | | Cool Rooms Open'gs, Lids, &c. | " | | | | | | |
| | | Scuppers | " | | | | | | |
| | | Cargo Hatchways | " | | | | | | |
| | | Hatches | " | | | | | | |
| | | Planking of Wood Vessels | — | | | | | | |
| | | Caulking ditto | — | | | | | | |
| | | Treenails ditto | — | | | | | | |
| | | Breasthooks & Stemson ditto | — | | | | | | |
| | | Transoms, Pointers, & Crutches ditto | — | | | | | | |
| | | Timbers of Frame at openings ditto | — | | | | | | |
| | | Ditto ditto at other places ditto | — | | | | | | |
| | | Stringers, Clamps & Shells ditto | — | | | | | | |
| | | Salting ditto | — | | | | | | |
| | | (State if examined.) | | | | | | | |
| | | Copper, or Y.M. of Wood Vessels | — | | | | | | |
| | | (State if on Fall) | | | | | | | |
| | | When put on, Month | | | | | | | |
| | | Year | | | | | | | |
| | | Boats | <i>Good</i> | | | | | | |
| | | Masts, Yards, &c. | " | | | | | | |
| | | Condition, how ascertained | <i>from dk</i> | | | | | | |
| | | (State if wedges removed) | <i>no</i> | | | | | | |
| | | Sails | <i>Good</i> | | | | | | |
| | | Equipment letter | — | | | | | | |
| | | Ancors, No. of | <i>3</i> | | | | | | |
| | | Cables (State if now ranged) | <i>no</i> | | | | | | |
| | | " length | — | | | | | | |
| | | (on board) | — | | | | | | |
| | | " Rule length | — | | | | | | |
| | | (per Table 22) | — | | | | | | |
| | | Hawsers & Warps | <i>Good</i> | | | | | | |
| | | Standing & Running Rigging | " | | | | | | |

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "..... to remain as now classed in the Register Book *without fresh record of Survey*," "to remain as classed and surveyed, 1-05," or "to remain as classed and to have record of survey, 1-05, and the notations of ss No. 1-05 and plnd05, &c."

This vessel is eligible in my opinion to remain as classed with fresh record of 7.07

Survey Fee (per Section 28)\$

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

.....19.....

Committee's Minute

TUES. JUL 23 1907

Character Assigned

Surveyor to Lloyd's Register of British & Foreign Shipping.
TUES. 5 MAY 1908

UES. 19 MAY 1908

FRI. 5 JUN 1969

Lloyd's Register
Foundation

W737-0058