

S. S. Woron

The Owners Superintendent should be informed of the Surveyors statements & that the notation of Special Survey No 2 cannot be made until the Survey has been completed & the necessary repairs to floor & intercostals in the Engine room tank carried out & this tank tested.

They should also be again informed that as the Special Survey, which is so much overdue, was not completed whilst the vessel was recently under Survey, a special general examination was made as required by the Circular relating to overdue Special Surveys recently issued by the Committee, with a view to the further postponement of the completion of the Survey & to a record of examination, with date, being made in the Register Book, and that the fee of 10 guineas charged for this examination is in accordance with the usual practice.

ARL

M  
10.7.17

Lowr Supr 10/7/17