

[Thin Copy for attaching to Report.]

REGIN.

's Register of Shipping.

Port Grunsky
23.8.39

Lis

With reference to the
now being held on the Steamer
No. "Responde"

inform you that, in consequence of
condition of this vessel's

new shaft liner

it is my duty to recommend to the Com-
mittee that the same be renewed

at the end of February 1940

as required for in the Rules, extracts from
which appear on the other side:—the con-

dition of the vessel's character in the
Register Book to be subject to the
provision of this condition.

I am,

Yours faithfully,

Clive Bell

Engineer Surveyor to Lloyd's Register.

Davison & Co. Ltd.

Hartlepool

Lloyd's Register
Foundation

376-0133